

Inspection Photos

API#045-06127

Operator: Maralex

Insp #: 692402899

Insp Date: 1/15/2021





Photo#1:
Overview of Location from entry to East.

January 15 , 2021



Photo#2:
Debris on site.



Photo#3:
Equipment stored on site.

January 15 , 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Rifle-Boulton API#045-06290



Photo#4:
Site is overgrown.



Photo#5:
Fence needing removed or repaired.

January 15 , 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Rifle-Boulton API#045-06290