

Inspection Photos  
Operator: Simcoe  
API: 067-07266  
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and crested wheatgrass observable through the snow.



Photo 3. View of the reference area comprised of irrigated grass field. Grasses are not in identifiable condition at this time.