

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2021

Submitted Date:

01/26/2021

Document Number:

699103041**FIELD INSPECTION FORM**Loc ID 460447 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460450	WELL	XX	12/31/2018		123-49385	State C24-730	ND
460451	WELL	XX	12/31/2018		123-49386	State C24-735	ND
460452	WELL	XX	12/31/2018		123-49387	State C24-717	ND
460453	WELL	XX	12/31/2018		123-49388	State C24-750	ND
460455	WELL	XX	12/31/2018		123-49390	State C24-745	ND
460456	WELL	XX	12/31/2018		123-49391	State C24-725	ND

General Comment:[Snow covered ground. Not drilled, appears to have no oil and gas activity.](#)

Inspected Facilities

Facility ID: 460450	Type: WELL	API Number: 123-49385	Status: XX	Insp. Status: ND
Facility ID: 460451	Type: WELL	API Number: 123-49386	Status: XX	Insp. Status: ND
Facility ID: 460452	Type: WELL	API Number: 123-49387	Status: XX	Insp. Status: ND
Facility ID: 460453	Type: WELL	API Number: 123-49388	Status: XX	Insp. Status: ND
Facility ID: 460455	Type: WELL	API Number: 123-49390	Status: XX	Insp. Status: ND
Facility ID: 460456	Type: WELL	API Number: 123-49391	Status: XX	Insp. Status: ND

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 1/26/21 at approximately 0839hrs, I, Inspector Adam Burns, Conducted an on-site inspection at C24-10 Pad of Noble Energy Location ID: 460447 in Weld County, Colorado.</p> <p>While there, I observed a well pad that is not drilled. Appears to have no oil and gas activity. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	01/26/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103042	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337173