

Final Reclamation Inspection

January 20, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 330864

Inspection Document #: 697502478

Weld County, CO

SWSW Section 16 T8N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864



Photo 1. Photo taken from the eastern access road, facing West. Photo illustrates the Operator has performed final reclamation activities (i.e., removal of gravel, straw mulch, seed, etc...). Desirable vegetation was observed throughout the access road but will remain in-process, as it has not achieved reference area levels.

Note: another adjacent road has been established after PA operations, not related to oil and gas.



Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864



Photo 2. Photo taken from the entrance to location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864




Photo 3. Photo taken from central well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864



Photo 5. Photo taken from the tank battery location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: State-Tincup #13-16
Location ID: 330864



Photo 6. Photo taken from the tank battery location, facing East. See comments under Photo 1.

