

# Final Reclamation Inspection

January 20, 2021

Operator: JUNIPER OIL AND MINING COMPANY - 44207

Location ID: 405695

Inspection Document #: 697502480

Weld County, CO

SWSE Section 16 T8N R59W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 1.** Photo taken from the entrance of the access road, facing South. Photo illustrates final reclamation activities have been conducted by Noble which were related to replugging two wells.



Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 2.** Photo taken from the eastern location, facing Southwest. See comments under Photo 1.



Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 3.** Photo taken from the eastern location, facing East. See comments under Photo 1.

