

Final Reclamation Inspection

January 20, 2021

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 407011

Inspection Document #: 697502482

Weld County, CO

SWSE Section 16 T8N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #1
Location ID: 407011



Photo 1. Photo taken from the entrance of the access road, facing South. Photo illustrates final reclamation activities have been conducted by Noble which were related to replugging two wells.



Inspection Photos
Location Name: STATE #1
Location ID: 407011



Photo 2. Photo taken from the eastern location, facing Southwest. See comments under Photo 1.



Inspection Photos
Location Name: STATE #1
Location ID: 407011



Photo 3. Photo taken from the eastern location, facing East. See comments under Photo 1.

