

Inspection Photos

1/26/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 468517

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 468517



Photo 1: Photo of valve can.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 468517



Photo 2: Continued from photo 1. Photo shows riser at valve can has been LO/TO

