

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE

Location ID: 334626



Photo #2723 from entrance to location.

Photo #2724 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE

Location ID: 334626



Photo #2725 Multiple wellheads signs weathered and not legible.



Photo #2726 Multiple wellheads signs weathered and not legible.