


TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



Rutting on location.



Rutting on location.



TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



Rutting on location.



Rutting on location.

TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



Rutting on location.



Rutting on location.

TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184



**Unmaintained straw bales running along
east edge of location.**



**Unmaintained straw bales running along
east edge of location.**

**TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184**



Equipment and materials on location not needed for production of wells.



Equipment and materials on location not needed for production of wells.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184**



PVC pipe over the edge of location.



PVC pipe over the edge of location.



**TEP ROCKY MOUNTAIN LLC
ARCO-66S96W 29NESE
Location # 335184**



Riling running off road running through location.



Riling running off road running through location.