

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2021

Submitted Date:

01/27/2021

Document Number:

693504321**FIELD INSPECTION FORM**Loc ID 419494 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419491	WELL	TA	04/01/2020	OW	123-32266	Peppler PC AA17-20	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 419491 Type: WELL API Number: 123-32266 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: At time of inspection flow lines have been removed and master valve is LOTO well is TA. Form 4 TA status is on file with the COGCC. NO MIT on file. Noble Energy's Alternative Mechanical Integrity Assurance Program.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Submit reports.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>Routine inspection.</u>	silverr	01/27/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693504322	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5338500