

Final Reclamation Inspection

January 28, 2021

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 329862

Inspection Document #: 697502492

Weld County, CO

NESE Section 1 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: QUARTER CIRCLE #1-918
Location ID: 329862



Photo 1. Photo taken from the well location, facing North. Photo illustrates Operator has removed all equipment from the well location. Well location has a land use change to housing development.

Inspection Photos
Location Name: QUARTER CIRCLE #1-918
Location ID: 329862



Photo 2. Photo taken from the associated offsite tank battery location, facing South. Photo illustrates Operator has removed all equipment from the tank battery location. Location has a land use change to housing development. Portions of the former tank battery are landscaped vegetation and a retention stormwater area.

Inspection Photos
Location Name: QUARTER CIRCLE #1-918
Location ID: 329862



Photo 3. Photo taken from the associated offsite tank battery location, facing South. See comments under Photo 2.