

# Inspection Photos

API: 071-09210

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/28/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021

## Inspection Photos



**Photo 1.** Facing northwest toward the access road which has not been recontoured. The gate remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021



## Inspection Photos



**Photo 2.** Facing north toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021

## Inspection Photos



**Photo 3.** Facing south toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021



## Inspection Photos



**Photo 4.** Facing toward the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021

## Inspection Photos



**Photo 5.** Facing west at the location which has not been recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09210 | Date: 1/28/2021



## Inspection Photos



**Photo 6.** A large berm remains t the southwest side of the location.

