

Inspection Photos
Location Name: Lilli Unit 2-8
Location ID: 326919



Colorado Oil and Gas Conservation Commission
40.67899, -103.87933, 4681.9ft, 246°
01/25/2021 14:57:42



Colorado Oil and Gas Conservation Commission
40.679, -103.8793, 4694.3ft, 235°
01/25/2021 14:57:31

Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Lilli Unit 2-8
Location ID: 326919



Photo 3 – Weeds have been cut – Please prevent future growth