

Inspection Photos
Operator: Simcoe
API: 067-08749
Date: 1/29/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Location largely snow covered. Taller perennial vegetation such as sand dropseed and rubber rabbitbrush observed through snow.



Photo 3. View of the reference area comprised of an irrigated grass field. Vegetation is largely snow covered at this time.