

Construction and Stormwater Inspection

January 28, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 474765

Inspection Document #: 697502494

Weld County, CO

SWNW Section 11 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: S&B /5-11HZ PAD
Location ID: 474765




Photo 1. Drone aerial imagery illustrates Operator has commenced construction activities by installing a ditch and berm BMP around the entire perimeter of location. The disturbance area is 33.5 acres.

Inspection Photos
Location Name: S&B /5-11HZ PAD
Location ID: 474765



Photo 2. Photo taken from the entrance of location, facing North. Photo illustrates current conditions along the frontage road. At the time of this inspection, no vehicle track out was observed.



Photo 3. Photo taken from the entrance of location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: S&B /5-11HZ PAD
Location ID: 474765



Photo 4. Photo taken from the western location, facing North. Photo illustrates the perimeter stormwater BMP-ditch and berm.



Photo 5. Photo taken from the southern location, facing Northeast. Photo illustrates a sediment trap in-process of being completed.

Inspection Photos
Location Name: S&B /5-11HZ PAD
Location ID: 474765



Photo 6. Photo taken from the western location, facing East. Photo illustrates the Operator is commencing topsoil salvage operations.



Photo 7. Photo taken from the southwestern location, facing North. Photo illustrates the location of the topsoil stockpile.