

# Final Reclamation Inspection

January 28, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 323564

Inspection Document #: 697502498

Weld County, CO

NWSW Section 11 T4N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Photo taken south of the well location, facing North. Photo illustrates a land use change to housing development. Based on aerial imagery, the well location appear to be in the backyard- see Photo 3.



**Photo 2.** Photo taken from the associated offsite tank battery location, facing South. Photo illustrates a land use change to housing development.



Inspection Photos  
Location Name: SEELE #1-11  
Location ID: 323564



**Photo 3.** Aerial imagery illustrates both the well and associated offsite tank battery location have undergone a land use change to housing development.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697502498