

Final Reclamation Inspection

January 28, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 323621

Inspection Document #: 697502500

Weld County, CO

SWSW Section 11 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SEELE #2-11
Location ID: 323621



Photo 1. Photo taken north of the well location, facing South. Photo illustrates a land use change to housing development. Based on aerial imagery, the well location appear to be in the backyard- see Photo 3.



Inspection Photos
Location Name: SEELE #2-11
Location ID: 323621



Photo 2. Photo taken from the associated offsite tank battery location, facing South. Photo illustrates a land use change to housing development.



Inspection Photos
Location Name: SEELE #2-11
Location ID: 323621



Photo 3. Aerial imagery illustrates both the well and associated offsite tank battery location have undergone a land use change to housing development.

