

Final Reclamation Inspection

January 29, 2021

Operator: Blue Chip Oil Inc- 8840

API: 05-123-13536

Inspection Document #: 697502506

Weld County, CO

NENE Section 25 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 1. Google Earth aerial imagery taken October 14, 2017, approximately 4 months after plugging and abandoning (P&A) the well. Photo illustrates the disturbance area (red line) that was mapped on September 10, 2018 using a Trimble Juno 3B handheld device that indicates an approximate disturbance of 1.23 acres.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 2. Photo taken from the western disturbance area, facing East. Photo illustrates the presence of Kochia, a weedy annual, throughout much of the area, which is not reflective of reference areas. Desirable perennial vegetation was observed within the Kochia establishment but has not establishment to reference area levels.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 3. Photo taken from the western disturbance area, facing North. See comments under Photo 2.



Photo 4. Photo taken from the northwestern disturbance area, facing East. The northwestern area does not have as much establishment of Kochia like the other disturbance areas.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 5. Photo taken from the southwestern disturbance area, facing West. See comments under Photo 2.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 6. Photo taken from the western access road, facing East. See comments under Photo 2. The red-dotted line outlines the disturbance area and the presence of Kochia which is not reflective of reference areas. Again, there was some desirable perennial vegetation observed within the Kochia establishment.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



01.29.2021 11:28

Photo 7. Photo taken from the central access road, facing East. See comments under Photo 6.



Photo 8. Close up photo taken from the access road illustrating the presence of desirable perennial vegetation within the Kochia establishment.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 9. Photo taken from the western well location, facing East. See comments under Photo 2 and 6.

Inspection Photos
Location Name: SLOAN #1
API: 05-123-13536



Photo 10. Photo taken from the well location, facing East. See comments under Photo 2 and 6.



Photo 11. Reference photo taken south of the access road, facing East. See comments under Photo 2.