

Inspection Photos

2/1/2021

Operator: CHEVRON USA INC - 16700

Location ID: 316448

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 1: Photo taken from the west end of the Location, facing northeast. Photos 1-3 provide an overview of the Location from northeast, southeast to south.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



20210201

Photo 4: Photo taken from the north end of the Location, facing south east. Photos 4-6 provide an overview of the Location from southeast, southwest to west.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 6: See comments under photo 4.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 7: Photo taken from the southwest corner of the Location, facing southwest. Photo shows area where gully erosion/head-cutting is occurring.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 8: Continued from photo 7. Photo shows gully erosion/head cut.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 9: Photo taken from the west end of the Location, facing south. Photo of slopes and interim areas of the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



20210201

Photo 10: Photo of wellhead/sign.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 316448



Photo 11: Photo shows example of marked anchors observed on Location.