

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: Union Pacific 22-32	Project No. 018-065
Description: Site entrance facing north.	<div data-bbox="418 331 1490 422">  </div> <div data-bbox="418 422 1490 464"> <p>☉ 17°N (T) ☉ 40.09729, -108.860527 ±4m ▲ 1576 m</p> </div>  <div data-bbox="1214 1094 1474 1129"> <p>22 Apr 2020, 11:27:29</p> </div>	
Description: Facing northeast.	<div data-bbox="418 1136 1490 1226">  </div> <div data-bbox="418 1226 1490 1268"> <p>☉ 68°NE (T) ☉ 40.097354, -108.860459 ±4m ▲ 1575 m</p> </div>  <div data-bbox="1214 1898 1474 1934"> <p>22 Apr 2020, 11:27:35</p> </div>	


PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: Union Pacific 22-32	Project No. 018-065
Description: Facing east. Salt/ alkaline crust is present in vehicle tracks.		
Description: Facing north.		

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: Union Pacific 22-32	Project No. 018-065
Description: Facing east.		
Description: Facing south.		

PHOTOGRAPHIC LOG

Project Name: 2020 RWSU On Site Spill Investigations	Site Location: Union Pacific 22-32	Project No. 018-065
Description: Facing southeast, towards the low area of the pad surface.		
Description: Facing southwest.	