

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #2785 from entrance to location.



Photo #2786 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



**Photo #2787 Flow line exhaust heating insulation open ended and not capped.**