

Inspection Photos
Location Name: Starck 33-18X
Location ID: 332620



Production facility



Wellhead

Inspection Photos
Location Name: Starck 33-18X
Location ID: 332620



Trash on 11/13/2020




Trash on 2/2/2021

Inspection Photos
Location Name: Starck 33-18X
Location ID: 332620



Unused equipment on 11/13/2020



Unused equipment on 2/2/2021

Inspection Photos
Location Name: Starck 33-18X
Location ID: 332620



Battery sign on 11/13/2020



Battery sign on 2/2/2021

Inspection Photos
Location Name: Starck 33-18X
Location ID: 332620



Trash on 11/13/2020



Trash on 2/2/2021