

Final Reclamation Inspection

January 29, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322730

Inspection Document #: 697502518

Weld County, CO

SESW Section 36 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 1. 2019 aerial imagery illustrates the well location access road that has not been reclaimed per Rule 1004.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 2. Photo taken from the entrance of the well location access road, facing South. Photo illustrates Operator has failed to reclaim the access road.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 3. Photo taken from a portion of the access road, facing South. Photo illustrates evidence of erosion occurring along the downslope portion of the access road.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 4. Photo taken from the southern access road, facing South. See comments under Photo 1.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 5. Photo taken from the northwestern well location, facing East. Photo illustrates the well location is in process. Some desirable perennial vegetation was observed but it is not reflective of reference area levels.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730




Photo 6. Photo taken from the western well location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 7. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 5.

Inspection Photos
Location Name: STATE #2-36
Location ID: 322730



Photo 8. Reference photo taken northwest of the location.