

Inspection Photos

Loc#334558

Operator: Caerus

Insp#: 692402951

Insp Date: 1/27/21





Photo#1:
Overview of Location to Northeast.

January 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Roles Loc#334593



Photo#2:
Interim area.



Photo#3:
Area behind Separators.

January 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Roles Loc#334558