

# *Inspection Photos*

*Loc#324402*

*Operator: Caerus*

*Insp#: 692402958*

*Insp Date: 1/27/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North.

January 27, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Brynildson Loc#324402



Photo#2:  
Perimeter berm.



Photo#3:  
Interim area.

January 27, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Brynildson Loc#324402