

Inspection Photos
Operator: Simcoe
API: 067-09715
Date: 1/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and intermediate wheatgrass observed through snow.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of open pasture, largely snow covered at this time.