

Inspection Photos
Operator: Logos
API: 067-05475
Date: 1/29/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and intermediate wheatgrass observed through snow.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of open pasture, largely snow covered at this time.