

Inspection Photos
Operator: Simcoe
API: 067-08425
Date: 1/29/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and intermediate wheatgrass observed through snow.



Photo 3. View of vegetation within the western project area. Approximately 50 Scotch and musk thistles observed.



Photo 4. View of the reference area comprised of open pasture, largely snow covered at this time.