

Inspection Photos
Operator: Simcoe
API: 067-06906
Date: 1/29/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass and rubber rabbitbrush observed through snow.




Photo 3. View of Russian knapweeds observed within the interim reclamation areas. Approximately 100 individuals observed.



Photo 4. View of the reference area comprised of open pasture, largely snow covered at this time.