

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402590214

Date Received:

02/03/2021

Spill report taken by:

YOUNG, ROB

Spill/Release Point ID:

479285

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>WESCO OPERATING INC</u>	Operator No: <u>95520</u>	<b>Phone Numbers</b>
Address: <u>120 S DURBIN STREET</u>		Phone: <u>(307) 5775329</u>
City: <u>CASPER</u>	State: <u>WY</u>	Zip: <u>82602</u>
Contact Person: <u>Dave Weinert</u>		Mobile: <u>( )</u>
		Email: <u>davew@kirkwoodcompanies.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402587379

Initial Report Date: 01/31/2021 Date of Discovery: 01/30/2021 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR NE SE SEC 27 TWP 3S RNG 51W MERIDIAN 6

Latitude: 39.762535 Longitude: -103.067703

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WASHINGTON

#### Reference Location:

Facility Type: TANK BATTERY

☐ Facility/Location ID No \_\_\_\_\_

Spill/Release Point Name: Rudnik injection pump

☐ Well API No. (Only if the reference facility is well) 05- -

☒ No Existing Facility or Location ID No.

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: sunny

Surface Owner: FEE

Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The packing on the injection pump failed. All spilled fluid stayed within containment. The spill volume is approximately 33 barrels of produced water. Fluid is being recovered by a vac truck and will be placed back into the on site tanks.

**List Agencies and Other Parties Notified:**

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

Was there damage during excavation? Yes ☐ No ☐

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

**SPILL/RELEASE DETAIL REPORTS**

#1 Supplemental Report Date: 02/03/2021

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	50	50	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 123 Width of Impact (feet): 47

Depth of Impact (feet BGS): \_\_\_\_\_ Depth of Impact (inches BGS): 4

How was extent determined?

The horizontal area is estimated by pumper (see the attached map provided by the pumper). The vertical depth is highly estimated as no excavation was completed as part of the spill cleanup.

**Soil/Geology Description:**

Water well location and depth to groundwater information taken from the Colorado DWR Well Permit Research Map Viewer. Well data is only for registered wells and has not been field verified. Depth to Groundwater is taken from the 1968 Water Well Filing for the nearest registered well. Soils information provided below was taken from NRCS Web Soil Survey. The soils are expected to be sandy loam and silt loam. Based on the information provided by the NRCS Web Soil Survey, the typical profile is 0-6" - sandy loam, 6-35 inches - sandy clay loam, 35-80 inches - sandy loam.

Depth to Groundwater (feet BGS) 115 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest	Water Well	3250	None <input type="checkbox"/>	Surface Water	1500	None <input type="checkbox"/>
	Wetlands		None <input checked="" type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
	Livestock	3300	None <input type="checkbox"/>	Occupied Building	1900	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

A produced water analysis is included.

Two photos of the spill are included.

A map of the spill area that was provided by the pumper is attached.

Per the approved Form 19, Wesco will collect four soil samples for analysis of pH, EC, SAR and Boron. Three of the samples will be collected within the spill area as shown on the attached map. The fourth sample will be a background sample collected within the berm, but outside of the spill area as indicated on the attached map. All of the soil samples will be collected from a depth of 0 - 4 inches below ground surface. The samples will be collected the week of February 8th - 12th.

The results of the analysis will be submitted to the COGCC via a form 19s.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Dave Weinert

Title: HSE Coordinator Date: 02/03/2021 Email: davew@kirkwoodcompanies.com

### COA Type

### Description

--	--

### Attachment List

#### Att Doc Num

#### Name

402590390	ANALYTICAL RESULTS
402590391	OTHER
402590891	OTHER

Total Attach: 3 Files

### General Comments

#### User Group

#### Comment

#### Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)