

Inspection Photos

API: 061-06353

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021

Inspection Photos




Photo 1. Facing north toward the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north toward the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021

Inspection Photos



Photo 3. The soils appear to be compacted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021

Inspection Photos



Photo 4. There is debris that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021

Inspection Photos



Photo 5. Facing west toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 2/2/2021