

Final Reclamation Inspection

February 3, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 306003

Inspection Document #: 697502522

Weld County, CO

NENE Section 36 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: TJADEN #36-11
Location ID: 306003



Photo 1. Photo taken from the tank battery location, facing East. Photo illustrates Operator has performed final reclamation activities and has performed weed management. Germination of desirable perennial vegetation was only observed along some portions of the access road.



Inspection Photos
Location Name: TJADEN #36-11
Location ID: 306003



Photo 2. Photo taken from the tank battery location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: TJADEN #36-11
Location ID: 306003



Photo 3. Photo taken from the eastern access road, facing West. See comments under Photo 1.



Inspection Photos
Location Name: TJADEN #36-11
Location ID: 306003



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: TJADEN #36-11
Location ID: 306003



Photo 5. Reference photo taken south of the access road, facing Southwest.

