

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2021

Submitted Date:

02/03/2021

Document Number:

696104275

FIELD INSPECTION FORM

Loc ID 302250 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297627	WELL	TA	05/27/2020	OW	123-28014	SHABLE 14-22	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.575892 / -104.509465

Abandoned Centralized Battery formerly served 5 Location IDs.
(302261, 302250, 302260, 302249, 306736).
(Well(s): 4: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

Location				
Lease Road:				
	Type Access			
comment:	Adequate			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
	Type PUMP JACK			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Protective shelter surrounds gas engine.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Gas engine powers pumping unit. Shut-down.			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 297627 Type: WELL API Number: 123-28014 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned: All Equipment Removed.
COGCC records indicate last production: 05/2016.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Form 4 Sundry doc. #402376745, Temporarily Abandoned | TA status date: 11/21/2018.
Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/08/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 206.
Submit current Brhd test. Comply w/ Rule 206.
Contact COGCC Engineering.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 02/03/2021 at approximately 14:24 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SHABLE /14-22 Location ID: 302250 Well Name: Shable 14-22 API: 05-123-28014 Location County: Weld County, Colorado Weather: Partly sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.575892 / -104.509465</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs. (302261, 302250, 302260, 302249, 306736). (Well(s): 4: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104276	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5344562