

Inspection Photos

Location Name: SHABLE-67N64W /14NWNW

Location #: 302249




Photo #1

Shable 14-25 (05-123-28013) Wellsite

Temporarily Abandoned | TA



Photo #2

Shable 14-24, 14-22, 14-23, 14-25 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Shable 14-11

Plugged & Abandoned | PA



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources