

Inspection Photos

Loc#335310

Operator: Caerus

Insp#: 692402964

Insp Date: 1/29/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Southeast.

January 29 2021

Caerus Benzal Loc#335310



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#2:
Rutting at Northwest perimeter of Pad.

January 29 2021



Photo#3:
Rutting at Northwest perimeter of Pad.

Caerus Benzel Loc#335310



Photo#4:
Degraded area behind tank.



Photo#5:
Area no longer needed for use.

January 29 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzal Loc#335310