

# *Inspection Photos*

*Loc#335312*

*Operator: Caerus*

*Insp#: 692402965*

*Insp Date: 1/29/21*





Photo#1:  
Overview of Location from lease road to Northeast.

January 29 2021




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Lazier Loc#335312



Photo#2:  
Leaking at base of tank.



Photo#3:  
Leaking valve.

January 29 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Lazier Loc#335312



Photo#4:  
Interim area.



Photo#5:  
Weedy area of pad.

January 29 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Lazier Loc#335312