

Inspection Photos

Loc#335385

Operator: Caerus

Insp#: 692402969

Insp Date: 1/29/21





Photo#1:
Overview of Location to Southwest.

January 29 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#335385



Photo#2:
Wellhead area..



Photo#3:
Fill slope and Interim area.

January 29 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#335385