

Inspection Photos

Loc#335344

Operator: Caerus

Insp#: 692402968

Insp Date: 1/29/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest and Wellhead area.

January 29 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#335344



Photo#2:
Rutting behind tanks.



Photo#3:
Interim area.

January 29 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#335344