

Inspection Photos

API: 061-06806

Operator: NEWELL ENERGY LTD

Inspection Date: 2/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing east toward the location. The location has not been reclaimed and vegetation has not established. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north toward the location. There are large areas of the location that have no vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 3. Facing west at the center of the location. This area is bare of vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 4. Facing south at the location. There are large areas of the location that have no vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 5. Location sign is laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing south toward the surrounding undisturbed pasture which consists of uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 2/2/2021