

Inspection Photos

Operator: Logos Operating
API: 067-05489
Date: 2/2/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Dense kochia debris up to 4.5 feet tall growing within the interim reclamation area.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Location largely snow covered. Taller perennial vegetation such as smooth brome observed through snow.



Photo 4. View of unused equipment within the project area.



Photo 5. View of the reference area comprised of open smooth brome pasture, largely snow covered at this time.