

Inspection Photos
Operator: Simcoe
API: 067-06911
Date: 2/2/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Vegetation largely snow covered at this time.



Photo 3. View of dense kochia debris growing along the northern fenceline.