

# Inspection Photos

Operator: Logos Operating  
API: 067-05486  
Date: 2/2/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northwestern project area facing northward. Weed debris observed at fencelines and around equipment.





Photo 3. View of dense kochia debris (up to 5 feet tall) growing along the southern fenceline.