

Inspection Photos
Operator: Simcoe
API: 067-06907
Date: 2/2/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Location largely snow covered. Perennial vegetation observed above snow, with western wheatgrass, sideoats grama, and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward. Inset shows Russian knapweed individual within the southeastern project area.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of sagebrush, mountain mahogany, and grasses/forbs-largely snow covered at this time.



Photo 5. View of closed gate after leaving location.