

Final Reclamation Inspection

February 3, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 305232

Inspection Document #: 697502536

Weld County, CO

NENE Section 6 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CECIL FARMS #6-11
Location ID: 305232



Photo 1. Photo taken from the associated offsite tank battery, facing North. Photo illustrates the tank battery location is now part of a new PDC location.



Inspection Photos
Location Name: CECIL FARMS #6-11
Location ID: 305232



Photo 2. Photo taken from the well location, facing West. Photo illustrates the well location is now part of a vegetated stormwater area for the new housing development. This section of land is within the City of Severance. A land use change to housing development is occurring to the west. This is now part of Lot 62 of the Golden Eagle Acres subdivision. There were no stormwater erosion or noxious weed issues observed.

