

Inspection Photos

Location Name: Zabka 1-15

API #123-13294



Wellhead

State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Document Number: 402580271
Date Received: 1/21/2021

Complete the Attachment Checklist

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL AND GAS ONSHORE LP
Address: 501 DIVISION BLVD
City: DENVER
State: CO
Zip: 80217-3778
Contact Name and Telephone: SABRINA FRANTZ
No: (970) 338-1139
E-mail: SABRINA_FRANTZ@OGCC.COM

API Number: 05-123-13294-00
OGCC Facility ID Number: Well/Facility Number: 1-15
Location (Circle): 08 SW, Section: 15 Township: 4N Range: 67W Meridian: _____
 SHUT-IN PRODUCTION WELL INJECTION WELL Last MIT Date: _____

Test Type:
 Test to Maintain SITA status 5-year LIC Reset Packer
 Verification of Repairs Annual UIC Test

Describe Repairs or Other Well Activities: _____

Wellbore Data at Time of Test		Casing Test	
Hydrocarbon/Producing Zone(s)	Perforated Interval:	Use when perforations or open hole is isolated by bridge plug or cement plug; use if cased-hole only with long back total depth.	
NI0BRARA, CODELL	6906-7012, 7216-7230'	Bridge Plug or Cement Plug Depth:	BRIDGE PLUG @ 6830'

Tubing Casing/Annulus Test			
Tubing Size:	Tubing Depth:	Top Packer Depth:	Multiple Packers?
2 3/8"	6730'		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Test Data				
Test Date	Well Status During Test	Casing Pressure Before Test	Initial Tubing Pressure	Final Tubing Pressure
2-4-21	SI	0		
Casing Pressure Start Test: 400	Casing Pressure - 5 Min: 400	Casing Pressure - 30 Min: 400	Casing Pressure Final Test: 400	Pressure Loss or Gain During Test: 0

Test Witnessed by State Representative? Yes No
OGCC Field Representative (Print Name): *Janetson*

Print Name: *Craig Lipsett*
Signed: *[Signature]*
OGCC Approval: _____ Title: _____
Conditions of Approval, if any: _____

Colorado Oil & Gas Conservation Commission
40.30655, -104.87893, 1455.0m, 271°
02/04/2021 12:04:42

Form 21