

URSA
Dixon B
Location # 311696



location



location

URSA
Dixon B
Location # 311696

Feb 4, 2021 at 10:50:16 AM
39.524113,-107.659472 ±30.90m
OGCC



location

Feb 4, 2021 at 10:51:00 AM
39.524505,-107.659642 ±4.79m
OGCC



Tank battery signage is missing information and
located at entrance of location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Dixon B
Location # 311696**



Unmarked dead man from previous inspection



Follow up photo shows dead man was attempted to be marked but not marked appropriately



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization




Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the cut slope



**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the cut slope

**URSA
Dixon B
Location # 311696**



Previous inspection photo of lack of stabilization




Follow up inspection photo shows that nothing has been done about the lack of stabilization on the cut slope

**URSA
Dixon B
Location # 311696**



Debris from previous inspection



Debris from follow up photo has not been removed



**URSA
Dixon B
Location # 311696**



Lack of stabilization



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources