

Grizzly Operating Stranahan 21B Location # 335440



location



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 21B Location # 335440



location



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Stranahan 21B
Location # 335440**



Previous inspection photo of lack of stabilization



**Follow up inspection photo shows that nothing has
been done about the lack of stabilization on the pad**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 21B Location # 335440



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 21B Location # 335440



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



Grizzly Operating Stranahan 21B Location # 335440



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 21B Location # 335440



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad

