

Grizzly Operating Friport Location # 322506



location



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Friport Location # 322506



location



location



Grizzly Operating Friport Location # 322506

Dec 10, 2020 at 1:58:42 PM
39.508704, -107.655005 ±4.77m
OGCC



Previous inspection photo of lack of stabilization

Feb 4, 2021 at 11:48:06 AM
39.508571, -107.655109 ±4.82m
OGCC



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Friport Location # 322506



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Friport Location # 322506



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources