

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2021

Submitted Date:

02/04/2021

Document Number:

698702448

FIELD INSPECTION FORM

Loc ID 327625 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247144	WELL	TA	05/27/2020	GW	123-14941	SCHMIDT 30-5G	TA
461005	LOCATION	AC	02/08/2019		-	Schmidt	AC

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 247144 Type: WELL API Number: 123-14941 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Facility ID: 461005 Type: LOCATION API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (2/4/21) at approximately (10:20 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (Schmidt 30-5G) (Noble Energy), at (Location #327625) in (Weld County) Colorado. While there, I observed a (TA Well) During this inspection no compliance issues were observed. No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	02/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702449	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345564