

Inspection Photos

API: 061-06821

Operator: BAYHORSE PETROLEUM LLC

Inspection Date: 2/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing south along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing south toward the location. The location has not adequately established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos




Photo 3. Facing east at the center of the location. This area is bare of vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos



Photo 4. Facing west at the center of the location. This area has sparse vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos




Photo 5. Facing north toward the location. The location has not adequately established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021

Inspection Photos




Photo 6. Facing east toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06821 | Date: 2/2/2021